

Report ID: 18,306,078 Version: 1 Created: 06 Aug 2018

Make:	Nissan	Model:	Wingroad	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2,007	Registration:		Reg Expiry:		Engine	1	<u> </u>	L	
WoF Expiry:	,	Odometer:	94,509 Kms	Good No:	18306078	Oil level	~			
VIN:	7AT0DH5GX18051094	Next Service:	104,501kms	Service Histor	y: No	Smoke & fumes	~		<u> </u>	
						Performance	~			
	port is not a warranty	eration is made	for any and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~			
						Performance	~			
Key:		-0		500-		Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
B = rust				710		Operation	~			
PT = paint defe	ect NP				101h	Noise	~			
C = crack						Clutch			~	
P = pin dent	HIP				74116	CV joints	~			
* = decals	- Alt	10		10		Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
		e				Performance	~			
Body Insr	pection Comments	Note: son	ne defects & blemishe	s may not be disp	played in the diagram	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread depth of tyres)				
						Left front	7 mr			
						Right front	7	7	mm	
						Left rear	7	7	mm	
Conditions During Body Inspection: Wet						Right rear	7 mm			
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Tidy .						Suspension performance	~			
						Steering performance	<			
S						Shock absorbers	~			
		Air Conditioning / Heater								
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpote	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dashboa	rd Good					Wipers (front & rear)	<			
	iu					Window winder FL	~			
						Window winder FR	~			
<u>General Comments</u>					Window winder RL	~				
Good wago	ui.					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Wet						Central locking	~			
Remote lock							~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspector	Inspected by: Daryll Timms Date: 06 Aug 2018									
Inspected by. Daryn minns Date: Vo Aug 2018										

I have read and understood this condition guide.

Name:

Signature: