

Report ID: 18,306,764 Version: 4 29 Nov 2018 Created:

Make:	Holden	Model:	Vectra	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2005	Registration:	CRD200	Reg Expiry:	09 May 2019	Engine			•
WoF Expiry:	27 Apr 2019	Odometer:	173,768 Kms	Good No:	18306764	Oil level	~		
VIN:	W0L0ZCF6851064437	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	DPT	-0	w w		S D	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	PT SC W			715	S D PT	Operation	~		
PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	110				게	CV joints	~		
* = decals	sc 916			-No-	ETTY S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S PT S S S S S S						Performance	~		
Dadute		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	-	oftvre	es)
Remote locking fail Windscreen stone chips									mm
	·					Right front		. <u>,</u> 5	 mm
						Left rear			mm
Conditions During Pody Inspection: Wet						Right rear		8 mn 5 mn	
Conditions During Body Inspection: Wet						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine oil le	-	•				Suspension performance		~	
						Steering performance	~	•	
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Poor						Head lights			
Seats									
Carpets	Carpets m	issing				Tail lights Indicators	v		
	Poor					Dashboard warning lights	~ ~		
Panels						Wipers (front & rear)			
Dashboa	rd Average					Window winder FL	v		
						Window winder FL Window winder FR	v		
General (Comments					Window winder FR Window winder RL	V		
Front suspension noisy						~			
Central lock						Window winder RR Rear view mirrors	v		
							V		
						Radio (basic test only)	~		
						CD (basic test only)			
						Number of keys	1		
Road Conditions During Test Drive: Wet Central locking								~	
Engine Tir	ming Mechanism:	Timing (- Thain			Remote locking		~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
				11113.		Reversing camera			~
Inspected by: Bobby Zhong Date: 29 Nov 2018									

I have read and understood this condition guide.

Name:

Signature: