

Basic Vehicle Condition Guide

Report ID: 18,307,028


Version:

Created: 08 Aug 2018

Make: Model: Corolla **Body Style:** Wagon Toyota Year: 2,007 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 01 Aug 2019 92,993 Kms 18307028 VIN: 7AT0H607X18026984 **Next Service:** 102000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Wet

Body Inspection Comments

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

01 Aug 2018 Inspected by: **Bobby Zhong** Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	7	.0	mm
Right front	7.0		mm
Left rear	7.0		mm
Right rear	7.0		mm
_		Yes	
Suspension			
Suspension performance	~		
Steering performance	V V		
Shock absorbers	~		
Air Conditioning / Heater			•
Operation	~		
Electrical / Accessories	•	•	
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	\(\times \) \(\t		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		•
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			./

Signature: