

Report ID: 18,307,156 Version: 1 13 Aug 2018 Created:

Make:	lsuzu	Model:	D-MAX	Body Style:	Utility		Pass	Fail	N/A	
Year:	2,012	Registration:	GNR992	Reg Expiry:	14 Oct 2018	Engine				
	2,012 12 Nov 2018	Odometer:	173,996 Kms	Good No:	14 Oct 2018 18307156	Oil level	~			
VIN:	MPATFR85JCT100653	Next Service:		Service Histor		Smoke & fumes	~		<u> </u>	
	MIFATER05JCT100055		181801		• 110	Performance	~		<u> </u>	
	port is not a warranty					Noise	v v			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.										
						Coolant condition Performance	~			
Key:	SD	-0	SP			Radiator / Hoses (visual)	~		-	
S = scratch	Sec	20		105	\mathbf{x}	Transmission	~			
D = dent				100	EID .					
R = rust	MIP			10	SHIF	Operation	~			
PT = paint defe	ect 1			+	SR	Noise Clutch	~			
C = crack P = pin dent	LHC		لالمار				~		<u> </u>	
* = decals	sc de					CV joints			~	
SC = stone chi	ps U			10		Wheel bearings	~			
W = significant scuffs						Brakes				
			S			Performance	~		<u> </u>	
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~			
Scratch left door mirror.Tray cover sign of wear.Stone chips front screen.					Tyres (lowest observed tread depth of tyres)					
						Left front	7	,	mm	
						Right front	7	,	mm	
						Left rear	6	5	mm	
Conditions During Body Inspection: Dry						Right rear	6	6 mm		
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
RWD. Sign o	of fluid leak rear diff plu	g.				Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Commonte						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good n Dr	ivers seat sign of	wear.			Head lights	~			
Carpote	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	Good					Wipers (front & rear)	~			
Dashboa	ru					Window winder FL	~			
						Window winder FR	~			
<u>General Comments</u>					Window winder RL			~		
Gear lever le	oose.					Window winder RR			~	
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Con	ditions During Test	t Drive:	Dry			Central locking			~	
	-		- • ,			Remote locking			~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected	d by: Eddie Marsters					Date: 13 Aug 20	18			

I have read and understood this condition guide.

Name:

Signature: