

Report ID: 18,307,517 Version: 2 Created: 02 Aug 2018

Make:	Honda	Model:	FIT	Body Style: Hatchback		Pass	Fail	N/A
Year:	2,013	Registration:		Reg Expiry:	Engine			1
WoF Expiry:	2,013 01 Aug 2019	Odometer:	83,133 Kms	Good No: 18307517	Oil level	~		
VIN:	7AT08G2YX18238799	Next Service:		Service History: No	Smoke & fumes			
	74106021716256799		95, TUUKIIIS	Schreefinstery. No	Performance	v		
Note: This re	port is not a warranty					~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						~		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Cooling System			
-					Coolant condition	~		
Key:					Performance	~		-
S = scratch					Radiator / Hoses (visual)			
D = dent					Transmission			
R = rust					Operation	~		
PT = paint def	ect	Noise	~					
C = crack					Clutch			~
P = pin dent * = decals					CV joints	~		
SC = stone chips					Wheel bearings	~		
W = significant scuffs					Brakes		1	
		\sim			Performance	~		
Body Ins	pection Comments	Note: son	ne defects & blemishes	may not be displayed in the diagram	Hand Brake	~		
					Tyres (lowest observed tread depth of tyres)			
					Left front	5.5 mm		mm
					Right front	5.5 mm		mm
					Left rear	6.	.5	mm
Conditions During Body Inspection: Wet					Right rear	6.5 mm		
Vici					Spare N/A			
Under Carriage & Under Bonnet Inspection Comments					Suspension			
					Suspension performance	~		
					Steering performance	~		
		Shock absorbers	~					
		Air Conditioning / Heater	1 1					
					Operation 🖌			
Interior Comments					Electrical / Accessories			
Seats	Good				Head lights	~		
	Good				Tail lights	~		
Carpets	Good				Indicators	~		
Panels	Good				Dashboard warning lights	~		
					Wipers (front & rear)	~		
Dashboa	Ird Good				Window winder FL	~		
	I				Window winder FR	~		
General Comments					Window winder RL	~		
					Window winder RR	~		<u> </u>
					Rear view mirrors	~		
					Radio (basic test only)	v		
					CD (basic test only) Number of keys		 	
						1		
Road Conditions During Test Drive: Wet Central locking								<u> </u>
Engine Ti	ming Mechanism	Timina	Chain		Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: Beversing camera								~
Evidence	ог сапт вен керіас	ement: N	lot Applicable	Kms:	Reversing camera			~
Inspected by: Ca Thach Date: 01 Aug 2018								

I have read and understood this condition guide.

Name:

Signature: