

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends **Cooling System**

a fuil mechanical inspection prior to purchase and this can be arranged for an additional charge.			Coolant condition	~		Γ
			Performance	~		┢
Key:	SPSC SPSC SSC		Radiator / Hoses (visual)	~		
S = scratch			Transmission	L		-
D = dent S SC	SPTC		Operation	~		
R = rust PT = paint defect			Noise	~		+
C = crack	SSC		Clutch	-		
P = pin dent			CV joints	~		+
* = decals S SC			Wheel bearings	V		+
SC = stone chips		_	Brakes			1
W = significant scuffs S SC			Performance	~		Ι
	Note: some defects & blemishes may not be displayed in the diagram		Hand Brake	~		+
body inspection comments			Tyres (lowest observed tread depth of tyre			
Minor stone chips in the windscreen ,front and rear bumpers need paint different colours ,rear wiper missing from boot lid ,			Left front	4 m		
			Right front		+ 1	m
			Left rear		+ 1	m
Conditions During I	Podulneportion w.	٦	Right rear		+ 1	m
Conditions During Body Inspection: Wet			Spare		+ Yes	
Under Carriage & Under Bonnet Inspection Comments			Suspension	L	res	
	•		Suspension performance	~		Τ
			Steering performance	~		+
			Shock absorbers	~		+
			Air Conditioning / Heater	•		
			Operation	~		Т
Interior Comments			Electrical / Accessories			
Seats	Average		Head lights	~		Т
			Tail lights	~		+
Carpets	Average		Indicators	~		+
Panels	Average		Dashboard warning lights	~		+
			Wipers (front & rear)	~		+
Dashboard	Average		Window winder FL	~		+
			Window winder FR	~		-
General Comments			Window winder RL			+
			Window winder RR	~		+
			Rear view mirrors	~		+
				~		╞
			Radio (basic test only)			
			CD (basic test only)	~		L
			Number of keys	2		1
Road Conditions During Test Drive: Wet			Central locking	~		1
		_	Remote locking	~		1

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable

Inspected by: Donovan Matara

06 Sep 2018 Date:

Sat. Nav. (basic test only)

Reversing camera

Report ID: 18,308,606 Version: 1 06 Sep 2018 Created:

Pass

V

V

V

V

Engine

Oil level

Noise

Smoke & fumes

Performance

Fail

N/A

~

mm mm mm mm

~

V

~

I have read and understood this condition guide. Name:

Kms:

Signature: