

Report ID: 18,308,702 Version: 1 Created: 06 Aug 2018

| Make: | Toyota | Model: | Caldina | Body Style: | SUV | | Pass | Fail | N/A |
|--|--------------------------|-----------------|------------------------|-------------------|----------------------|--|------|--------|----------|
| Year: | 2,007 | Registration: | | Reg Expiry: | | Engine | | | |
| WoF Expiry: | | Odometer: | 52,292 Kms | Good No: | 18308702 | Oil level | ~ | | |
| VIN: | 7AT0H624X18031020 | Next Service: | 62,288kms | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | aration is made | for ago and milaago | Darte have not | been dismonthed or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | | | | |
| a full mechan | ical inspection prior to | purchase and tl | nis can be arranged fo | r an additional o | charge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | GIE | | | 1n- | | Operation | ~ | | |
| R = rust PT = paint defe | | | | \prod | JHIH | Noise | ~ | | |
| C = crack | | | | + | | Clutch | • | | ~ |
| P = pin dent | | | | | | CV joints | ~ | | • |
| * = decals | - Mik | | | AL. | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs | | | | | | Performance | ~ | | |
| | | Note: con | Ledefects & blemishes | may not be disr | layed in the diagram | Hand Brake | | | |
| Body Insp | pection Comments | 1016.3011 | le delects & blemisnes | may not be disp | dayed in the diagram | | | ofture | () () |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 5 | | mm |
| | | | | | | Right front | 4 | | mm |
| | | | | | | Left rear | 5 mm | | |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 4 mm | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare | Yes | | |
| | | | | | | Suspension | | | |
| Tidy . | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| Shock absorbers | | | | | | | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| Interior Comments | | | | | | Operation 🖌 | | | |
| Good | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| Carpets | Good | | | | | Tail lights | ~ | | |
| | Card | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Good | | | | | Wipers (front & rear) | ~ | | |
| | | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General Comments | | | | | | Window winder RL | ~ | | |
| Tidy wagon | I. | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Wet Central locking | | | | | | | | | |
| | - | | | | | Remote locking | ~ | | |
| - | ming Mechanism: | Timing (| Chain | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | |
| | | | | | | | | | |
| Inspected by: Daryll Timms Date: 06 Aug 2018 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: