

Report ID: 18,308,815 Version: 1 Created: 06 Aug 2018

Make:	Subaru	Model:	Impreza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,007	Registration:	· • · · · · · · · · · · · · · · · · · ·	Reg Expiry:		Engine	I		L
WoF Expiry:		Odometer:	26,836 Kms	Good No:	18308815	Oil level	~		
VIN:	7AT0GF09X18007502	Next Service:	36,000	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		f	Danta have a st	harry discovered and an	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechar	ical inspection prior to	purchase and t	his can be arranged fo	r an additional o	harge.	Coolant condition	~		[
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
D = dent	6/6			The		Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack	ect			+		Clutch			~
P = pin dent						CV joints	~		
* = decals	- MIK			AL-		Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs									
		Nata				Performance	~		
Body Ins	pection Comments	Note: son	ne defects & blemishes	may not be disp	hayed in the diagram	Hand Brake		<u> </u>	Ļ
						Tyres (lowest observed tread depth of tyres)			
						Left front	7.	.0	mm
						Right front	7.	.0	mm
[Left rear	7.	.0	mm
Conditions During Body Inspection: Dry						Right rear 7.0 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Under Ca	irriage & Under Bor	inet inspectio	on comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories		-	
Seats	Good					Head lights	~		
Caract	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ira					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	V		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
L							1		L .
Inspected by: Mathew Varghese Date: 02 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: