

Basic Vehicle Condition Guide

Report ID: 18,308,964


Version:

Created: 08 Aug 2018

Make: Model: Nissan Cube **Body Style:** Hatchback Year: 2,007 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 01 Aug 2019 18308964 68,238 Kms VIN: 7AT0DH63X18064412 **Next Service: Service History:** 78,200kms

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Ca Thach Date: 03 Aug 2018

	Pass	Fail	N/A
Engine	ı		
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	٧ ٧		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes	1		
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	6.0		mm
Right front	6.0		mm
Left rear	6.0		mm
Right rear	6.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	1		1
Operation	~		
Electrical / Accessories	1		1
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V V V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			'

I have read and understood this condition guide.

Name:

Signature: