

Report ID: 18,310,053 Version: 1 Created: 04 Sep 2018

Make:	Holden	Model:	Captiva 7	Body Style:	SUV		Pass	Fail	N/A	
Year:	2,015	Registration:	JLM713	Reg Expiry:	16 Dec 2018	Engine	1	l	L	
WoF Expiry:		Odometer:	123,759 Kms	Good No:	18310053	Oil level	~			
VIN:	KL3CD2659FB052077	Next Service:	137,000kms	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechar	lical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~			
	W S		WP		W	Performance	~			
Key:	IN IS	\sim		5(0)-		Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
R = rust SSCW						Operation	~			
PT = paint defect						Noise	~			
C = crack						Clutch			~	
P = pin dent						CV joints	~			
						Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
						Performance	~			
Body Insi	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
<u> </u>						Tyres (lowest observed tread depth of tyres)				
						Left front	3.	.6	mm	
						Right front	2	.8	mm	
						Left rear	2	.6	mm	
Conditions During Body Inspection: Dry						Right rear	2.8 mm			
						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Front brake	pads will need to be re	placed soon				Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Commonte						Operation 🖌				
Interior Comments Good						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpets	Good					Tail lights	~			
	Cood					Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dashboa	Good					Wipers (front & rear)	~			
						Window winder FL	~			
Ganard	ommonts					Window winder FR	~		 	
	<u>Comments</u>					Window winder RL	~		<u> </u>	
						Window winder RR	~			
						Rear view mirrors	~		<u> </u>	
						Radio (basic test only)	~		ļ	
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Wet						Central locking	~			
Engine Timing Mechanism: Timing Chain						Remote locking	~		<u> </u>	
						Sat. Nav. (basic test only)	~			
Evidence	огсант вен керіас	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspecte	Inspected by: Jason Young Date: 04 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: