

Basic Vehicle Condition Guide

Report ID: 18,310,167

Pass

1

V

/

V

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

Created: 06 Aug 2018

Fail

N/A

1

mm

mm

mm

mm

4.0

4.0

4.0

1

/

/

1

1

1


Yes

Make: Model: **Body Style:** SUV Subaru Forester Year: 2,005 Registration: **Reg Expiry:** WoF Expiry: **Odometer: Good No:**

02 Aug 2019 88,800 Kms 18310167 VIN: **Next Service: Service History:** 7AT0GF17X18093863 98700

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection:

Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Xinghui Lin

I have read and understood this condition guide.

Evidence of Cam Belt Replacement: No

	Remote locking	'			
	Sat. Nav. (basic test only)	~			
Kms:	Reversing camera	~			
Date: 05 Aug 2018					
Name: Signature:					