

Basic Vehicle Condition Guide

Report ID: 18,310,200


Version:

Created: 03 Aug 2018

Make: Model: Nissan Pulsar **Body Style:** Hatchback Year: 2,001 Registration: Reg Expiry: AJH686 19 Sep 2018 WoF Expiry: **Odometer: Good No:** 18310200 26 Sep 2018 202,150 Kms VIN: SJNFAAN16U0189313 **Next Service: Service History:** 202992

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor stone chips in the windscreen,

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

03 Aug 2018 Inspected by: Donovan Matara Date:

Name:

| | Pass | Fail | N/A | |
|--|-----------------|------|----------|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | <i>y y</i> | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | <i>v</i> | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | \(\triangle \) | | | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 1.5 | | mm | |
| Right front | 2 | | mm | |
| Left rear | 4 | | mm | |
| Right rear | 1.5 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | \(\triangle \) | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | <i>'</i> | | | |
| Window winder FL | <i>'</i> | | | |
| Window winder FR | ~ | | | |
| Window winder RL | <i>v</i> | | | |
| Window winder RR | ' | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 1 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | | ' | |

Signature: