

Report ID: 18,310,608 Version: 1 Created: 06 Aug 2018

Make:	Nissan	Model:	Wingroad	Body Style: Wagon		Pass	Fail	N/A
Year:	2,005	Registration:	Wingroud	Reg Expiry:	Engine			
	01 Aug 2019	Odometer:	53,346 Kms	Good No: 18310608	Oil level	~		
VIN:	7AT0DH5GX18000680		63,341kms	Service History: No	Smoke & fumes	~		
			05,5418113		Performance	~		
	port is not a warranty				Noise	~		
This report is diagnostic ter	Cooling System							
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.								
					Performance	~		
Key:		-0			Radiator / Hoses (visual)	ン ン		
S = scratch					Transmission			
D = dent								
R = rust	-MIP				Operation	~		
PT = paint defe	ect M				Noise	~		
C = crack P = pin dent	III				Clutch			~
* = decals	dic				CV joints	~		
SC = stone chi	ps V	10			Wheel bearings	~		
W = significan	/	Brakes						
					Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be displayed in the diagram	Hand Brake	~		
					Tyres (lowest observed tread depth of tyres)			
					Left front	5	5	mm
					Right front	5	5	mm
					Left rear	7	7	mm
Conditions During Body Inspection: Wet					Right rear	7 mm		mm
					Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension			
Tidy .					Suspension performance	~		
					Steering performance	~		
Shock ab						~		
					Air Conditioning / Heater	1		1
					Operation	~		
Interior Comments					Electrical / Accessories			
Seats	Good				Head lights	~		
	Good				Tail lights	~		
Carpets	Good				Indicators	~		
Panels	Good				Dashboard warning lights	~		+
					Wipers (front & rear)	~		+
Dashboa	rd Good				Window winder FL	~		+
					Window winder FR	~		
General Comments					Window winder RL	~		
Good wago					Window winder RR	~		
					Rear view mirrors	~		+
					Radio (basic test only)	~		
					CD (basic test only)			
		Number of keys	✓					
								1
Road Conditions During Test Drive: Wet Central locking								<u> </u>
Engine Tir	ming Mechanism:	Timina	Chain		Remote locking			~
Fuidence of Com Belt Donle comparts								~
LVIGENCE	or carri bert neplac		lot Applicable	11113.	Reversing camera			~
Inspected by: Daryll Timms Date: 06 Aug 2018								

I have read and understood this condition guide.

Name:

Signature: