

Report ID: 18,311,301 Version: 1 Created: 03 Aug 2018

Make:	Hyundai	Model:	Tucson	Body Style:	SUV		Pass	Fail	N/A
Year:	2,007	Registration:	DWS47	Reg Expiry:	22 Oct 2018	Engine	1 455	·un	
WoF Expiry:	25 Oct 2018	Odometer:	264,420 Kms	Good No:	18311301	Oil level	~		
VIN:	KMHJN81DR7U57291	Next Service:	201,1201113	Service Histor		Smoke & fumes	· ·		
					,	Performance	~		
	port is not a warranty	avation is made	for one and miles as	Danta hava nat	heen discontlad or	Noise		~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-	SD	Radiator / Hoses (visual)	~		
S = scratch						Transmission	-		
D = dent R = rust	sc			The	SD SD	Operation	~		
PT = paint def				$\left[ \right] \left[ \right]$		Noise	V		
C = crack						Clutch			~
P = pin dent	HID				7414	CV joints	~		-
* = decals	sc 91			The second		Wheel bearings	V		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Body Ins	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Front park light not working						Tyres (lowest observed tread depth of tyres			es)
LR & RR brake light lens damaged						Left front 6			mm
						Right front		2	mm
						Left rear	1		mm
Conditions During Body Inspection: Wet						Right rear			mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine oil l	eaks					Suspension performance		~	
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		1
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights		~	
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)		>	
Dashboa	iiu y					Window winder FL	~		
	_					Window winder FR	~		
General Comments					Window winder RL	~			
Engine nois Front suspe	sy(tapping) ension knocking noise					Window winder RR	~		
Wheel alignment needed(cannot go straight)						Rear view mirrors	~		
Wiper need	d replacement					Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Timing Mechanicmy Controls						Remote locking		~	
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspected by: Bobby Zhong Date: 03 Aug 201							18		
I have read	and understood th	is condition o	iuide. Name: .			Signature:			