

Report ID: 18,311,412 Version: 1 Created: 05 Aug 2018

Make:	Mazda	Model:	E1800	Body Style:	Van		Pass	Fail	N/A
Year:	2,011	Registration:	FWK373	Reg Expiry:	26 Oct 2018	Engine			
WoF Expiry:	09 May 2019	Odometer:	196,617 Kms	Good No:	18311412	Oil level	~		
VIN:	JM0SKW08200304817	Next Service:	203,000	Service Histor	y: Yes	Smoke & fumes	~		
N						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechai	lical inspection prior to	purchase and ti	his can be arranged ic		.narge.	Coolant condition	~		
	SC		* *		SC	Performance	~		
Key:		=(0)		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust SC PR						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch	~		
P = pin dent	sc dle				2414	CV joints			~
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scurrs SC D*W S*						Performance 🖌			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	and Brake 🖌		
						Tyres (lowest observed tread depth of tyres)			
						Left front	2	2	mm
						Right front	3	3	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Dry						Right rear		3	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
		Operation	~						
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
	_					Window winder FR	~		
General Comments						Window winder RL			~
Engine oil l	eak					Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Mathew Varabese									
Inspected by: Mathew Varghese Date: 05 Aug 2018									
I have read and understood this condition guide. Name:									