

Report ID: 18,311,956 Version: 1 Created: 07 Aug 2018

Make:	Nissan	Model:	Fuga	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,005	<b>Registration:</b>		Reg Expiry:		Engine	1		
WoF Expiry:	,	Odometer:	56,210 Kms	Good No:	18311956	Oil level	~		
VIN:	7AT0DH8GX18215091	Next Service:	66000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust				715	HIV	Operation	~		
PT = paint defe		r I		$\left( \left  \left( \right) \right\rangle \right)$	70H	Noise	~		
C = crack						Clutch			~
P = pin dent	HID				7414	CV joints			~
* = decals	- Alt			To .		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	7.	.0	mm
						Right front	7.	.0	mm
						Left rear	7.	.0	mm
Conditions During Body Inspection: Wet						Right rear	7.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	۲		
						Indicators	۲		
Panels	Good					Dashboard warning lights	2		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Bobby Zhong Date: 06 Aug 2018									

I have read and understood this condition guide.

Name: .....