

Report ID: 18,312,247 Version: 1 Created: 06 Aug 2018

Make:	Hyundai	Model:	lload	Body Style:	Van		Pass	Fail	N/A
Year:	2,015	Registration:	JAA361	Reg Expiry:	27 Feb 2019	Engine		-	
WoF Expiry:	15 Jan 2019	Odometer:	108,657 Kms	Good No:	18312247	Oil level	~		
VIN:	KMFWBX7KLEU68336	Next Service:	106430	Service Histor		Smoke & fumes	~		
			100130		110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	P	-0	SD SD			Radiator / Hoses (visual)	~		
S = scratch	Se	20		105	X	Transmission	V		
D = dent	IS AL			100	BID	Operation			1
R = rust				10		Noise	レ レ		
PT = paint def C = crack	ect			+	S D R SC	Clutch	-		
P = pin dent	Ho	KI			االلا		~		
* = decals	sc pp			SI_	Ell'As	CV joints	~		
SC = stone chi	ps US	LA		()))		Wheel bearings Brakes	~		<u> </u>
W = significant scuffs									I
		Notorer	ne defects & blemishes		laved in the diagram	Performance Hand Brake	v		
Body Insp	pection Comments	Note: som	ie delects & blemisnes	may not be disp	layed in the diagram			<i>C</i> .	Ļ
						Tyres (lowest observed tread depth of tyres)			
						Left front	7		mm
						Right front	7		mm
						Left rear	6 mm		-
Conditions During Body Inspection: Dry						Right rear	3 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	inage & onder bor	metinspectic	<u>on comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Interior Comments drivers seat holes						Electrical / Accessories			
Seats	unvers sea	it noies				Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
-	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: John Lindsay Date: 06 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: