

Report ID: 18,312,559 Version: 1 Created: 06 Aug 2018

Make:	Toyota	Model:	HIACE 2.0ZR VAN	Body Style:	Van		Pass	Fail	N/A
	1,991	Registration:	LCW409	Reg Expiry:	10 Jul 2018	Engine		-	
<u>-</u> .	03 Feb 2019	Odometer:	251,007 Kms	Good No:	18312559	Oil level	~		
VIN:		Next Service:		Service Histor		Smoke & fumes	~		
			·			Performance	~		
	ort is not a warranty		f	Dauta have used	harry alternational and	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:		™ (m)	SPW SRW	-161-	S P W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	sw bl			TIS	SW	Operation	~		
PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack					S W	Clutch	~		
P = pin dent	HIS				74114	CV joints	-		~
* = decals	RSC 916			-No-	SDRPW	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SW SDPW SDPW SDW						Performance	~		
Podylaca	action Commonto	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Plastic trim on left rear guard missing. Has hub caps on both left side wheels & right side wheels have plastic						Tyres (lowest observed tread depth of tyres)			25)
centre caps.								mm	
						Right front	5.		mm
						Left rear	4.		mm
Conditions During Body Inspection: Dry					Right rear	4.0 mm		mm	
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Steering performance							~		
Shock absorbers									
						Air Conditioning / Heater	itioning / Heater		
						Operation			~
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboar	d					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			~
Hole in fabri	c on drivers seat base	& foam in worn o	ut on right edge of sea	ət.		Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conc	litions During Tes	t Drive:	Dry			Central locking	~		
	-		-			Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence o	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Increased	by: Jason Young					Date: 06 Aug 20	1.0		
Inspected by: Jason Young Date: 06 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: