

Basic Vehicle Condition Guide

Report ID: 18,312,690


Version:

Created: 10 Aug 2018

Make: Model: Mazda Atenza **Body Style:** Sedan Year: 2,009 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 02 Aug 2019 78,208 Kms 18312690 VIN: 7AT0C139X18102369 **Next Service: Service History:** 88,204kms

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy.

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Nice tidy Atenza sedan.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Daryll Timms Date: 10 Aug 2018

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	~			
Noise	V V			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	'			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	>			
Tyres (lowest observed tread depth of tyres)				
Left front	5		mm	
Right front	5		mm	
Left rear	6		mm	
Right rear	6		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	v			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	V			
Indicators	~			
Dashboard warning lights	V V			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	/			
Radio (basic test only)	'			
CD (basic test only)	~			
Number of keys	1		1	
Central locking				
Remote locking	'			
Sat. Nav. (basic test only)			'	
Reversing camera			'	

Signature: