

## **Basic Vehicle Condition Guide**

Report ID: 18,313,336

Pass

1

~

/

V

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

**Transmission** 

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Right front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 06 Aug 2018

Fail

N/A

1

mm

mm

mm

mm

7

3.5

4.5

1

/

/

/

1

1

4 1

~


~

Yes

Make: Hyundai Model: **Body Style:** Sonata Sedan Year: Registration: **Reg Expiry:** 2,004 CCW847 29 Dec 2018 WoF Expiry: **Odometer: Good No:** 09 Jan 2019 199,507 Kms 18313336 VIN: KMHEN41DR4A01174 **Next Service: Service History:** 205000 Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

## **Under Carriage & Under Bonnet Inspection Comments**

FWD. Engine fluid leak. Both outter CV boots leaking grease. Surface rust under carriage. Exhaust leak.

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

## **General Comments**

Engine oil level on low mark. Both remote not working. Coolant rusty n radiator cap faulty.

**Road Conditions During Test Drive:** Dry

**Engine Timing Mechanism:** Cambelt **Evidence of Cam Belt Replacement:** Kms: No

Inspected by: **Eddie Marsters** Date: 06 Aug 2018

Na	me:	Signature:	

I have read and understood this condition guide.