


Make:	LDV	Model:	V80	Body Style:	Van
Year:	2,016	Registration:	JWU83	Reg Expiry:	15 Jun 2019
WoF Expiry:	13 Jun 2019	Odometer:	52,675 Kms	Good No:	18313554
VIN:	LSKG5GL10FA236299	Next Service:		Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:

S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Wipers not working correctly. Electrical contacts on both rear doors not fitted correctly and damage on rubber beside LR door. Dents on rear inner guards. RF door and RF guard are damaged by door opening too far, also rattle inside RF door. RF mirror base damaged, Stonechips on windscreen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Power steering reservoir cap not sealing well. Engine has oil seepage. Spare tyre bald.

Interior Comments

Seats	Poor
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Small dents in both L&R sills below sliding doors. No towbar tongue.
Automatic shifter not working correctly, not always holding in neutral. Wear on RF seat. Seats have marks.
Sometimes difficult to start because of shifter issue.
Drives ok.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
Cooling System			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand Brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	8	mm	
Right front	9	mm	
Left rear	4	mm	
Right rear	5	mm	
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Roger King

Date: 05 Sep 2018

I have read and understood this condition guide.

Name:

Signature: