

Basic Vehicle Condition Guide

Report ID: 18,314,061


Version:

Created: 10 Oct 2018

Make: Model: **Body Style:** Utility Mazda **Bounty** Year: Registration: Reg Expiry: 1999 YP6222 11 Jan 2019 **WoF Expiry: Odometer:** 17 Feb 2019 **Good No:** 18314061 200,955 Kms VIN: MM0UNY0W10011136 **Next Service: Service History:** 210,952kms No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Clear coat lifting off bonnet. Stone chips in windscreen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Pinion seal on rear diff is damp

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Good | | |

General Comments

Indicator not turning off on its own when going around a corner. Large hole in right side edge of base on drivers seat.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Kms: Yes 100,263

Inspected by: Date: 07 Aug 2018 Jason Young

| | Pass | Fail | N/A | |
|---|----------------------------|---------|-----|--|
| Engine | | | | |
| Oil level | > | | | |
| Smoke & fumes | V V | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ' | | | |
| Noise | ' | | | |
| Clutch | ~ | | | |
| CV joints | <i>y y y</i> | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | > | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed treac | l depth | of tyre | es) | |
| Left front | 7 | .4 | mm | |
| Right front | 8 | .6 | mm | |
| Left rear | 8 | .8 | mm | |
| Right rear | 8.4 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | | | ~ | |
| Electrical / Accessories | | | | |
| Head lights | <i>\</i> | | | |
| Tail lights | • | | | |
| Indicators | • | | | |
| Dashboard warning lights | • | | | |
| Wipers (front & rear) Window winder FL | V V V V V V | | | |
| | • | | | |
| Window winder FR | • | | | |
| Window winder RL Window winder RR | <i>V</i> | | | |
| Rear view mirrors | | | | |
| | | | | |
| Radio (basic test only) CD (basic test only) | • | | ./ | |
| Number of keys | 1 | | | |
| Central locking | 1 | | | |
| Remote locking | • | | ., | |
| Sat. Nav. (basic test only) | | | ., | |
| Reversing camera | | | ./ | |
| neversing carriera | | | | |

I have read and understood this condition guide.

Name:

Signature: