

Basic Vehicle Condition Guide

Report ID: 18,315,041


Version:

Created: 07 Aug 2018

Make: Model: ΚIΑ RIO **Body Style:** Hatchback Year: 2,008 Registration: EUB763 Reg Expiry: 22 Dec 2018 **WoF Expiry: Odometer: Good No:** 18315041 18 Apr 2019 138,844 Kms VIN: KNADE243386374665 **Next Service: Service History:** 145000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Damage left and right sill Right wing mirror cover broken Left taillight cracked Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Underbody oxidisation

Interior Comments			
Seats	stains		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

No rear seats ,seat belts or storks

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 135,000

Inspected by: John Lindsay Date: 07 Aug 2018

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	<i>v</i>			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	\(\triangle \)			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front		6	mm	
Right front		6	mm	
Left rear		5	mm	
Right rear		5	mm	
Spare		Yes		
Suspension			1	
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories	1			
Head lights	~			
Tail lights		~		
Indicators	<i>'</i>			
Dashboard warning lights	<i>'</i>			
Wipers (front & rear)	•			
Window winder FL	\(\triangle \)			
Window winder FR	•			
Window winder RL	-			
Window winder RR	~			
Rear view mirrors	V			
Radio (basic test only)	<i>'</i>			
CD (basic test only) Number of keys	<u> </u>			
Central locking	1			
Remote locking		./		
Sat. Nav. (basic test only)			./	
Reversing camera			1	
neversing camera				

Signature: