

Report ID: 18,315,664 Version: 1 14 Aug 2018 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,007	Registration:	HSS498	Reg Expiry:	27 Oct 2018	Engine	I	I	I
WoF Expiry:	,	Odometer:	190,216 Kms	Good No:	18315664	Oil level	~		
VIN:	7AT0C13JX14310703	Next Service:	151,446	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	S SC W	-0	SC S SC	-161-	S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation 🖌			
R = rust PT = paint defect						Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints	~		•
* = decals SSC 919 SSC						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S SC S SC W S SC						Performance	~		
Noto: como defecto 8 blemichos may not be dienlayed in the diagram						Hand Brake	~		
Body Inspection Comments							-	ofture))
Radio needs band expander					Tyres (lowest observed tread depth of tyres)				
						Left front		.8	mm
						Right front Left rear	-1.0		mm
						5.0		mm	
Conditions During Body Inspection: Dry						Right rear	5.9 mm		
Under Carriage & Under Bonnet Inspection Comments					Spare Yes				
Rear wheels bent					Suspension				
Engine oil leak						Suspension performance		~	
Under body surface rust						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats	, it cluge					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	-					Window winder FL	~		
Ganaral						Window winder FR	~		
General Comments Vehicle has vibration on road test					Window winder RL	~			
Veniere nus	vibration on roug test					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism:						Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Ian Dunn Date: 07 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: