

Basic Vehicle Condition Guide

Report ID: 18,316,126


Version: 1

Created: 08 Aug 2018

Make: Model: Honda Odyssey **Body Style:** Wagon Year: 2,008 Registration: Reg Expiry: **WoF Expiry: Odometer: Good No:** 18316126 06 Aug 2019 126,666 Kms VIN: 7AT08G61X18411442 **Next Service: Service History:** 137,000

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:	Dry	

Under Carriage & Under Bonnet Inspection Comments

Interior Comment	<u>S</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Mathew Varghese Date: 08 Aug 2018

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System	•	•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	•	•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	d depth	of tyre	es)
Left front	6	 5	mm
Right front	6	 5	mm
Left rear	6	5	mm
Right rear	6	5	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater			l
Operation	~		
Electrical / Accessories	<u> </u>		
Head lights	V		
Tail lights	·		
Indicators	·		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	<i>'</i>		
Rear view mirrors	<i>'</i>		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys			
Central locking	2		
Remote locking	<i>y</i>		
Sat. Nav. (basic test only)			-
-	.,		
Reversing camera	'		

Signature: