

Basic Vehicle Condition Guide

Report ID: 18,316,142


Version:

Created: 09 Aug 2018

Make: Model: Caldina **Body Style:** SUV Toyota Year: 2,006 Registration: Reg Expiry: **WoF Expiry: Odometer: Good No:** 73,912 Kms 06 Aug 2019 18316142 VIN: 7AT0H624X18030506 **Next Service:** 83000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

08 Aug 2018 Inspected by: **Bobby Zhong** Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•		
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	5	.0	mm
Right front	5	.0	mm
Left rear	6.0		mm
Right rear	6.0		mm
Spare	Yes		
Suspension	1		
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			ļ
Operation	~		
Electrical / Accessories			I
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Window winder FL	~		
Window winder FR	\(\times \)		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	·		
Remote locking	~		
Sat. Nav. (basic test only)			V
Reversing camera			V
eversing camera			

Signature: