

Report ID: 56,081 Version: 1 Created: 14 Sep 2018

Make:	Holden	Model:	Cruze	Body Style:	Sedan		Pass	Fail	N/A
Year:	2010	Registration:	FFY597	Reg Expiry:	14 Jan 2019	Engine	1	I	
WoF Expiry:	12 Oct 2018	Odometer:	91,280 Kms	Good No:	18316458	Oil level	~		
VIN:	KL3JA695JAK593527	Next Service:	Just Serviced	Service History	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	sc	-0	ls			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SC SC WS						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch	•		~
P = pin dent	Ho					CV joints	~		-
* = decals	sc PK			AL-	ELTR DS	Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs SC S						Performance			
		Note: con			laved in the diagram	Hand Brake			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								~ f t	
							Tyres (lowest observed tread depth of tyres		
					Left front	1.0		mm	
						Right front		.0	mm
						Left rear	4.0		mm
Conditions During Body Inspection: Wet						Right rear	4.0 n		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder boi	inet inspectio	<u>on comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dashboa	Ira					Window winder FL	~		
	_					Window winder FR	~		
General (<u>Comments</u>					Window winder RL		~	
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		•
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
							1	1	
Inspected by: DM Date: 10 Aug 2018									
I have read and understood this condition guide. Name:									