

Report ID: 18,316,663

Pass

1

~

V

1

V

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

CV joints

Wheel bearings

Coolant condition Performance

Radiator / Hoses (visual)

Created: 07 Aug 2018

Fail


~

N/A

Make: Model: C4 **Body Style:** Hatchback Citroen Year: Registration: **DBP181 Reg Expiry:** 2,005 29 Aug 2018 **WoF Expiry: Odometer: Good No:** 10 Oct 2018 127,274 Kms 18316663 VIN: **Next Service: Service History:** VF7LCRHRH74239200 120000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Glovebox catch broken. Front bumper right cover missing. Mirrors need painting. Hail damage

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

No bonnet prop

Interior Comments			
Seats	Good		
Carpets	Poor		
Panels	Good		
Dashboard	Good		

Name:

General Comments

Inspected by:

Noise in engine pulley area. Engine check light on

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Brian Hill

Evidence of Cam Belt Replacement: Kms: No

Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front mm 6 Left rear 8 mm Right rear mm 6 Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) Reversing camera

07 Aug 2018

Signature:

I have read a	nd understo	od this cond	ition guide.