

Report ID: 18,318,037 Version: 2 Created: 04 Sep 2018

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A
Year:	2,012	Registration:	GPJ714	Reg Expiry:	29 Jan 2019	Engine			
WoF Expiry:	18 Dec 2018	Odometer:	139,018 Kms	Good No:	18318037	Oil level	~		
VIN:	KMHSH81XSCU90509	Next Service:	143000	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		6	Danta harra nat	haan diamanda daa	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	V		
Key:	S	-0	SC			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent S = suct S SC D D F S							Operation 🖌		
R = rust PT = paint defect						Noise	~		
C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	6/16			-NL	ETTP S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S S S S						Performance	~		
		Note: som		may not be disp		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread depth of tyres)			() ()
						Right front	6		mm
						Left rear	6		mm
			_			Right rear	6		
Conditions During Body Inspection: Dry						Spare	7.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Yes			
Tidy						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	-		
						Air Conditioning / Heater	~		
Interior Comments						Operation			
						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights Indicators	~		
	Good						V		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear) Window winder FL	V		
							V		
General (<u>Comments</u>					Window winder FR Window winder RL	V		
						Window winder RL Window winder RR	V		
							~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Ti	ming Mechanism:	Timing				Remote locking	~		
						Sat. Nav. (basic test only)			~
			lot Applicable	11113.		Reversing camera			~
Inspected by: Stuart Melbourne Date: 10 Aug 2018									

I have read and understood this condition guide.

Name: