

Report ID: 18,318,102 Version: 1 Created: 09 Aug 2018

Make:	Honda	Model:	Stream	Body Style:	SUV		Pass	Fail	N/A
Year:	2,009	Registration:		Reg Expiry:		Engine	1		I
WoF Expiry:		Odometer:	82,657 Kms	Good No:	18318102	Oil level	~		
VIN:	7AT08GADX18000817	Next Service:	,	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty	anation is mode	for any and miles as	Danta hava nat	hoon dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional	charge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission	-		
D = dent	- HE			TIN		Operation	~		
R = rust PT = paint def				\prod		Noise	~		
C = crack						Clutch	-		~
P = pin dent	-110				74114	CV joints	~		-
* = decals	616			The		Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs	$\neg \varnothing$				Performance	~		
Dedular		Note: som	ne defects & blemishes	may not be dis	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
					Left front 4				
						Right front			mm
						Left rear		1	mm
Conditions During Body Inspection: Dry					Right rear	4 mm		mm	
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension				
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			I
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets	0000					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	I					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		I
Road Conditions During Test Drive: Wet						Central locking	· •		
			wel			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Bobby Zhong Date: 09 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: