

Report ID: 18,319,286 Version: 2 Created: 11 Oct 2018

Make:	Volkswagon	Model:	Caddy	Body Style:	Van		Pass	Fail	N/A
Year:	Volkswagen 2011	Registration:	Caddy FYN887	Reg Expiry:	van 29 Aug 2019	Engine	1 435	i uli	
WoF Expiry:	13 Oct 2018	Odometer:	170,084 Kms	Good No:	29 Aug 2019 18319286	Oil level	~		
VIN:	WV2ZZZ2KZBX26570(170,004 KIIIS	Service Histor		Smoke & fumes	~		
•					· N0	Performance	~		<u> </u>
	port is not a warranty					Noise	~		
	a guide only. Conside sting undertaken. The					Cooling System	v		
	ical inspection prior to					Coolant condition			1
		_				Performance	ン ン		
Key:	S	-0	s s		D	Radiator / Hoses (visual)	~		-
S = scratch	Se	20		10/2	X	Transmission	V		
D = dent	IS AL			1 - L	HID DW				1
R = rust				10		Operation	~		
PT = paint def C = crack	ect			+	SC	Noise Clutch	~		
C = Crack P = pin dent	Ho								~
* = decals	sc dr			SI_	Ell'As	CV joints	~		
SC = stone chi	ps US			10		Wheel bearings	~		
W = significant scuffs						Brakes			
						Performance	~		
<u>Body Ins</u>	pection Comments	Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		<u> </u>
FL door power switch not working upwards						Tyres (lowest observed tread depth of tyres)			
Rear both doors sliding glasses not opening/ closing Rear seat back rest not locking						Left front	4	ŀ	mm
Spare tyre o	5					Right front	e	;	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Wet						Right rear	5 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
<u>Under Ca</u>	inage & onder bor	inet inspectic	on comments			Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			. <u> </u>
Interior Comments						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
- ·	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
Left side fo	otstep needs attention					Window winder RR			~
						Rear view mirrors	<		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
			-			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			r
Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 12	20,361	Reversing camera			r
						<u> </u>			
Inspecte	d by: Mathew Varghe	se				Date: 11 Oct 20	18		
I have read	and understood th	is condition a	uide. Name: .			Signature:			