

Report ID: 18,319,818 Version: 2 14 Aug 2018 Created:

Make:	Mazda	Model:	CX-7	Body Style:	SUV		Pass	Fail	N/A
Year:	2,010	Registration:	JNM104	Reg Expiry:	29 Sep 2018	Engine			
WoF Expiry:	2,010 26 Jan 2019	Odometer:	146,231 Kms	Good No:	18319818	Oil level	~		
VIN:	JM0ER10L200216869	Next Service:	148,000	Service Histor		Smoke & fumes	~		
	500210005		140,000		. 110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	S	-0	s s		sc	Radiator / Hoses (visual)	~		
S = scratch	STO	A CO			X	Transmission			L
D = dent	IS ALL			The	BID	Operation	~		
R = rust				10	JHIL	Noise	~		
PT = paint def C = crack				+	SC	Clutch			~
P = pin dent	Ho					CV joints	~		
* = decals	PSC PIC			AL-		Wheel bearings	-		
SC = stone chi	ps U	20		JAL)		Brakes	~		L
W = significan	t scuffs	-	S S		Is	Performance			<u> </u>
		Note: son	ne defects & blemishes			Hand Brake	~ ~		<u> </u>
Body Insp	pection Comments	1016.301	le delects & blemisnes	s may not be disp	layed in the diagram			ofturo	
					Tyres (lowest observed tread depth of tyres)				
						Left front	3.		mm
						Right front Left rear	3.	-	mm
							6.		mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage a onder boi	meemspeede	<u>Comments</u>			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats	, iverage					Head lights	~		<b> </b>
Carpets	Average					Tail lights	~		<b> </b>
	Average					Indicators	~		<b> </b>
Panels	Average					Dashboard warning lights	~		<b> </b>
Dashboa	rd Good					Wipers (front & rear)	~		<b> </b>
						Window winder FL	~		<b> </b>
Ganaral	omments					Window winder FR	~		<b> </b>
General Comments 1 key remote not working					Window winder RL	~		<b> </b>	
	te not working					Window winder RR	~		<b> </b>
						Rear view mirrors	~		<b> </b>
						Radio (basic test only)	~		<b> </b>
						CD (basic test only)	~		
L						Number of keys	1		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		<b> </b>
Enging Ti	ning Machanism	<b>T</b> '. '				Remote locking	~		<b> </b>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Mathew Varghese Date: 12 Aug 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....