

## **Basic Vehicle Condition Guide**

Report ID: 51,881


Version:

Created: 21 Aug 2018

Make: Model: Mini **Body Style:** Hatchback Cooper Year: 2,007 Registration: Reg Expiry: JGG640 02 Nov 2018 **WoF Expiry: Odometer: Good No:** 18320307 15 Aug 2019 76,803 Kms VIN: WMWMF72090TV0002 **Next Service: Service History:** Just Serviced No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

## **General Comments**

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: DM Date: 10 Aug 2018

Pass	Fail	N/A		
		1		
~				
~				
~				
•				
~				
~				
~				
~				
~				
		~		
~				
~				
_				
~				
~				
Tyres (lowest observed tread depth of tyres)				
3.	.0	mm		
3.0		mm		
3.0		mm		
3.0		mm		
Spare N/A				
~				
~				
~				
Air Conditioning / Heater				
Operation 🗸				
~				
~				
~				
~				
v_				
		1		
~				
~		V		
~		<i>V</i>		
~		<i>V</i>		
<i>V</i>		<i>V</i>		
\( \times \)		<i>V</i>		
v v v		<i>V</i>		
V V V V V		v v		
V V V V V		\(\nu\)		
V V V V V		\(\nu\)		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	プログライン マンファイン マンファイン マンファイン マンファイン マンファイン マンファイン は depth of tyre 3.0 3.0 3.0 3.0 N/A		

I have read and understood this condition guide.

Name: .....

Signature: .....