

Report ID: 18,320,471 Version: 2 Created: 24 Aug 2018

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,013	Registration:	JHU434	Reg Expiry:	08 Mar 2019	Engine			·
WoF Expiry:	06 Mar 2019	Odometer:	51,563 Kms	Good No:	18320471	Oil level	~		
VIN:	7AT0GK0CX15216916	Next Service:	51574	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	unting is mode	for and miles as	Dauta hava nat	heen dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc di			The		Operation	~		
R = rust PT = paint defe				r I M	JHIH	Noise	~		
C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	sc 916			AL.	EII PR-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	he defects & blemishes	may not be disn	laved in the diagram	Hand Brake	~		
Body Insp	ection Comments	10000.3011	le delects & blemisnes	indy not be disp	ayed in the diagram		-	oftwo	
					Tyres (lowest observed tread depth of tyres)				
						Left front	6.	-	mm
						Right front Left rear	6.		mm
							3.	-	mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
Tidy	inage a onder bor	meenspeede	<u>eominents</u>			Suspension			
l						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		I
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	Stanis					Head lights	~		
Carpets	Average					Tail lights	~		
- ·	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Canaral						Window winder FR	~		
General	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
	ning Machanisme					Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Stuart Melbourne Date: 09 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: