

Report ID: 18,322,940 Version: 1 Created: 21 Aug 2018

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A
Year:	2,014	Registration:	HKS579	Reg Expiry:	06 Nov 2018	Engine			L
WoF Expiry:		Odometer:	71,445 Kms	Good No:	18322940	Oil level	~		
VIN:	KMHST81XSEU308990	Next Service:	75,000kms	Service Histor		Smoke & fumes	~		
			75,0001115			Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:	w Iw	-0			w	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation	1 1 1		
R = rust				10	JHIH	Noise	~		
PT = paint defe C = crack				+		Clutch	~		~
P = pin dent	Ho				JUII —	CV joints	~		V
* = decals	sc PIC			AL-		Wheel bearings	~		
SC = stone chips						Brakes			<u> </u>
W = significant scuffs S W W									
		Notor com	Lefects & blemishes			Performance	~		
Body Insp	pection Comments	Note: son	le délects & biemisnes	may not be disp	layed in the diagram	Hand Brake		. ( .	
						Tyres (lowest observed tread depth of tyres)			
						Left front	8.8		mm
						Right front	8.8	8	mm
						Left rear	8.8		mm
Conditions During Body Inspection: Dry						Right rear	8.8 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	mage & onder bor	inet inspectic	<u>In comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
	•					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking									
Remote locking							~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Jason Young Date: 20 Aug 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....