

Basic Vehicle Condition Guide

Report ID: 18,322,964


Version:

Created: 12 Aug 2018

Make: Model: **BMW** 1 Series **Body Style:** Hatchback Year: 2,016 Registration: KEE398 Reg Expiry: 18 Feb 2019 WoF Expiry: **Odometer: Good No:** 03 Nov 2019 18322964 28,118 Kms VIN: WBA1S32040V801110 Next Service: **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Xinghui Lin Date: 12 Aug 2018

Name:

			1
	Pass	Fail	N/A
Engine		ı	
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System		1	1
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	~		
Brakes		ı	
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	d depth	of tyre	es)
Left front	4	4	mm
Right front	4		mm
Left rear	3.5		mm
Right rear	3.5		mm
Spare		N/A	
Suspension			
Suspension performance	~		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater		ı	1
Operation	~		
Electrical / Accessories	ı	I	
Head lights	~		
Tail lights	~		
Indicators	V		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1	ı	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)	~		
Reversing camera	~		

Signature: