

## **Basic Vehicle Condition Guide**

Report ID: 18,323,689

**Pass** 

~

~

/

V

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 13 Aug 2018

Fail

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

6

6

6

1

/

/

1

1

1


1

Yes

Make: Model: Volkswagen **EOS Body Style:** Convertible Year: Registration: **Reg Expiry:** 2,006 **KWT899** 04 Oct 2018 **WoF Expiry: Odometer: Good No:** 24 May 2019 122,345 Kms 18323689 VIN: **Next Service: Service History:** WVWZZZ1FZ7V00614 135000 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Clean

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

**General Comments** 

**Road Conditions During Test Drive:** Dry

**Engine Timing Mechanism:** Cambalt

Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No	Kms:	Sat. Nav. (basic test only) Reversing camera	V	•
Inspected by: Stuart Melbourne		Date: 13 Aug 20	)18	
nave read and understood this condition guide.	Name:	Signature:		