

Basic Vehicle Condition Guide

Report ID: 18,323,881


Version:

Engine

Created: 17 Aug 2018

> Fail N/A

Make: Model: **Body Style:** Hyundai Grandeur Sedan Year: 2,009 Registration: EUT843 Reg Expiry: 20 Apr 2019 WoF Expiry: Odometer: Good No: 05 Jul 2019 142 567 Kms 18323881



Ca Thach

Inspected by:

Evidence of Cam Belt Replacement: No

I have read and understood this condition guide.

	Central locking	'								
	Remote locking	~								
	Sat. Nav. (basic test only)		~							
Kms:	Reversing camera		~							
Date: 17 Aug 2018										
Name: Signature:										

W	oF Expiry:	05 Jul 2019	Odometer:	142,567 Kms	Good No:	18323881		Oil level	~		
٧	IN:	KMHFC41VR8A328678	Next Service:	153,000kms	Service Histor	y: Yes		Smoke & fumes	~		
_								Performance	~		
		port is not a warranty a guide only. Conside	eration is made	for age and mileag	e. Parts have not	been dismantled o	r	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System					
d	Tuli mechan	ical inspection prior to	purchase and ti	iis can be arranged i	or arradultional C	inarge.		Coolant condition	~		
	_			SP S		SD		Performance	~		
	(ey: = scratch		=(O)		5(0)=			Radiator / Hoses (visual)	~		
	= scratch = dent	SE				AD	_	Transmission		!	
_	= rust						J	Operation	~		
	Γ = paint defe	ect NP					_	Noise	~		
C	= crack					11111	┙	Clutch			~
	= pin dent	- HR					2.2	CV joints	~		
	= decals	z Alb						Wheel bearings	~		
	C = stone chi I = significant	/	$\mathbb{V}(\mathbb{Q})$		$\leq (0)$	~	Brakes				
vv	– sigillicari	S D PT		S D PT S D		SD		Performance	~		
	Rody Inst	pection Comments	Note: son	ne defects & blemishe	es may not be disp	layed in the diagram		Hand Brake	~		
	Dody IIIsp	ocction comments						Tyres (lowest observed tread depth of tyres)			
								Left front		7	mm
								Right front		 7	mm
								Left rear	4	.5	mm
	Condition	ns During Body Ins	nection:	Wet			٦	Right rear	4	.5	mm
Conditions Burning Body Inspection. Wet				4	Spare		Yes				
Under Carriage & Under Bonnet Inspection Comments					Suspension						
	Engine oil le	eak						Suspension performance	~		
								Steering performance	~		
								Shock absorbers	~		
								Air Conditioning / Heater			ļ.
						Operation					
	Interior C	<u>omments</u>						Electrical / Accessories			
	Seats	Good						Head lights	~		
	_	Average						Tail lights	~		
	Carpets							Indicators	~		
	Panels	Good						Dashboard warning lights	~		
		Good						Wipers (front & rear)	~		
	Dashboa	rd Good						Window winder FL	~		
		•					4	Window winder FR	~		
	General C	<u>Comments</u>						Window winder RL	~		
								Window winder RR	~		
								Rear view mirrors	~		
								Radio (basic test only)	~		
								CD (basic test only)	~		
						Number of keys	2	<u> </u>	1		
Road Conditions During Test Drive: Wet Central locking			·								
Remote locking				1							
	Engine Tir	ming Mechanism:	Cambel	t				Sat. Nav. (basic test only)			~
							- 1	·		1	1