

Report ID: 18,324,761 Version: 3 10 Sep 2018 Created:

Make:	Mazda	Model:	Mazda3	Body Style:	Sedan	1Г		Pass	Fail	N/A	
Year:	2,014	Registration:	HSM372	Reg Expiry:	20 Oct 2018	E	Engine				
WoF Expiry:	21 Sep 2019	Odometer:	97,501 Kms	Good No:	18324761		Oil level	~			
VIN:	JM0BM523810148733	Next Service:	99,000kms	Service Histor	y: Yes		Smoke & fumes	~			
						٦ſ	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Jŀ	Coolant condition	~			
						٦٢	Performance	~			
Key:		-0	S D		s		Radiator / Hoses (visual)	~			
S = scratch							Transmission				
D = dent	s dl			ZIN	HILL		Operation	~			
R = rust PT = paint defe				$\left(\left \right\rangle \right)$			Noise	~			
C = crack					SC]	Clutch	-		~	
P = pin dent					세비	IF	CV joints	~			
* = decals	sc 916			-Jul	ETTY S	۱ŀ	Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs W S D							Performance	~			
		Nata an	ne defects & blemishes	may not be disr			Hand Brake	v v			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								-	oftyre	 ><)	
Windscreen stone chips Front left tyre outer wall damage							Tyres (lowest observed tread depth of tyres)				
	re outer wan aamage						Right front		.5	mm	
							Left rear		.5	mm	
						╡┝			.5	mm	
Conditions During Body Inspection: Dry						┛┝	Right rear 5.5 mm				
Under Carriage & Under Bonnet Inspection Comments						٦ŀ	Spare Yes				
	mage & onder boi	met inspectio	<u>on comments</u>				Suspension				
							Suspension performance	~			
							Steering performance	~			
							Shock absorbers	~			
							Air Conditioning / Heater				
Interior Commonts							Operation	~			
Interior Comments						E	Electrical / Accessories				
Seats	Good						Head lights	~			
Carpote	Carpets m	issing					Tail lights	~			
Carpets							Indicators	~			
Panels	Good						Dashboard warning lights	>			
	Good						Wipers (front & rear)	>			
Dashboa	ra						Window winder FL	>			
						╡Ӷ	Window winder FR	~			
<u>General Comments</u>							Window winder RL	~			
Performance maintenance light on							Window winder RR	~			
							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	~			
						┘┞	Number of keys	2	1	1	
Road Conditions During Test Drive: Dry						٦٢	Central locking	~			
						╧┠	Remote locking	~			
Engine Timing Mechanism: Timing Chain							Sat. Nav. (basic test only)	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:							Reversing camera	~			
	-							÷			
Inspected by: Mathew Varghese Date: 10 Sep 2018											

I have read and understood this condition guide.

Name:

Signature: