

Report ID: 18,325,151 Version: 1 14 Aug 2018 Created:

Make:	Ford	Model:	Mondeo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,004	Registration:	CGT583	Reg Expiry:	01 Jul 2019	Engine			
WoF Expiry:	26 Apr 2019	Odometer:	215,917 Kms	Good No:	18325151	Oil level	~		
VIN:	WF05XXGBB54K10618	Next Service:	216000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
diagnostic te	sting undertaken. The v	ehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
			S P SC S P SC			Performance	~		
Key:	S SC S	-0	S P SC S P SC	505	S SC	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	s sc			710	HIV	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIR				74 <u>11</u> 4	CV joints	~		
* = decals	sc 916			To .		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D SC S S						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
					Left front 7 mi				
						Right front		7	mm
						Left rear	-		mm
Conditions During Body Inspection: Wet						Right rear		7	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	V		
						Air Conditioning / Heater	1		
L						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	drivers sea	t side trim broke	n,stains,worn,			Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Car shudde	rs when idling ,					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Unknown Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 14 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: