

Basic Vehicle Condition Guide

Report ID: 18,327,117

Version: 2

Created: 11 Nov 2018

Make: Model: Volkswagen Golf **Body Style:** Hatchback

Year: 2009 Registration:

Reg Expiry:


WoF Expiry: 11 Jul 2019 **Odometer:** 72,888 Kms **Good No:** 18327117

VIN:

WVWZZZ1KZ9U01238 Next Service: **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A	
Engine Engine				
Oil level	×			
Smoke & fumes	×			
Performance	×			
Noise	×			
Cooling System				
Coolant condition	×			
Performance	×			
Radiator / Hoses (visual)	×			
Transmission	ı			
Operation	×			
Noise	×			
Clutch			×	
CV joints	×			
Wheel bearings	×			
Brakes				
Performance	×			
Hand Brake	×			
Tyres (lowest observed tread depth of tyres)				
Left front	į	5	mm	
Right front	Į	5	mm	
Left rear	į	5	mm	
Right rear	5		mm	
Spare		Yes		
Suspension				
Suspension performance	×			
Steering performance	×			
Shock absorbers	×			
Air Conditioning / Heater				
Operation 🗶				
Electrical / Accessories				
Head lights	×			
Tail lights	×			
Indicators	×			
Dashboard warning lights	×			
Wipers (front & rear)	×			
Window winder FL	×			
Window winder FR	×			
Window winder RL	×			
Window winder RR	×			
Rear view mirrors	×			
Radio (basic test only)	X			
CD (basic test only)	×			
Number of keys	2			
Central locking	X			
Remote locking	×			
Sat. Nav. (basic test only)			×	
Reversing camera			×	

I have read and understood this condition guide.

Xinghui Lin

Name:

Signature:

11 Nov 2018

Date: