

Basic Vehicle Condition Guide

Report ID: 18,327,268

Version:


Created: 15 Aug 2018

Make: Model: Nissan Tiida **Body Style:** Hatchback Year: 2,008 Registration: Reg Expiry:

WoF Expiry: Odometer: Good No: 10 Aug 2019 93,024 Kms 18327268 VIN: 7AT0DH78X18193005 **Next Service:** 103,019kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy.

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

C	<u></u>
uenerai	Comments

Nice hatch.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

Date: 15 Aug 2018 Inspected by: **Daryll Timms**

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			1
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission			ı
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	<u> </u>	7	mm
Right front	7		mm
Left rear	7		mm
Right rear		, 7 mn	
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			ļ.
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V		
Wipers (front & rear)	<i>v</i>		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1	l	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~
-		1	

I have read and understood this condition guide.

Name:

Signature: