

Report ID: 18,327,487 Version: 1 Created: 05 Sep 2018

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A	
Year:	2,008	Registration:		Reg Expiry:		Engine			L	
WoF Expiry:		Odometer:	115,880 Kms	Good No:	18327487	Oil level	~			
VIN:	7AT0CJ3MX18202916	Next Service:	125879	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	oration is made	for any and milaage	Darts have not	boon dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	Coolant condition			
						Performance	~			
Key:		-0		-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission			L	
D = dent R = rust	- HE			715	HIL	Operation	~			
PT = paint defe				$\left[\left(\right) \right]$		Noise	~			
C = crack				$+ \mathbf{\nabla}$		Clutch			~	
P = pin dent	HID				7414	CV joints	~			
* = decals	- Alf			-Jul-		Wheel bearings	~			
SC = stone chips						Brakes				
W = significan	t scuffs w					Performance	~			
Body Incr	Dection Commonts	Note: som	ne defects & blemishe	s may not be disp	blayed in the diagram	Hand Brake	~		<u> </u>	
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	1 2S)	
						Left front			mm	
						Right front		1	mm	
						Left rear		1	mm	
Conditions During Body Inspection: Dry						Right rear			mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater			L	
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets	0000					Indicators	~			
Panels	Good					Dashboard warning lights	~			
	. Good					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
	1				i	Window winder FR	~			
General Comments						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1	I	1	
Road Conditions During Test Drive: Wet						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
Inspecte	Inspected by: John Lindsay Date: 05 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: