

Basic Vehicle Condition Guide

Report ID: 18,327,661


Version:

Created: 05 Sep 2018

Make: Model: IS350 **Body Style:** Lexus Sedan Year: Registration: **Reg Expiry:** 2,007 WoF Expiry: **Odometer: Good No:** 09 Aug 2019 103,452 Kms 18327661 VIN: **Next Service: Service History:** 7AT0B00HX18011895 113448

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>	
Seats	Good
Carpets	Good
Panels	Average
Dashboard	Average

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

Inspected by: John Lindsay

Name:

Fail N/A Pass Engine Oil level Smoke & fumes 1 Performance V Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front 7 mm Left rear 7 mm Right rear mm 7 Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera 1

Date:

05 Sep 2018

Signature: