

Basic Vehicle Condition Guide

Report ID: 18,328,596


Version:

Created: 15 Aug 2018

Make: Model: **Body Style:** Subaru Legacy Wagon Year: Registration: **Reg Expiry:** 2,009 **WoF Expiry: Odometer: Good No:** 15 Aug 2019 119,745 Kms 18328596 VIN: **Next Service: Service History:** 7AT0GF0BX18010639 129743 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>	
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Xinghui Lin

Evidence of Cam Belt Replacement: Yes

Kms:

Name:

98,361

Fail N/A **Pass** Engine Oil level Smoke & fumes 1 Performance V Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front 4 mm Left rear 4 mm Right rear mm 4 Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 2 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera

Date:

15 Aug 2018

Signature: