

Report ID: 18,328,842 Version: 1 17 Aug 2018 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2,012	Registration:	LNF83	Reg Expiry:	10 Sep 2018	Engine	I	<u> </u>	
WoF Expiry:	06 Sep 2018	Odometer:	228,397 Kms	Good No:	18328842	Oil level	~		
VIN:	MMAJRKA40CD01554	Next Service:	237,000kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
			•			Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SPSC	-0	*W *	-161-	SC W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SC W S S S S S S S S S S S S S S S S S						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent	HID				세비	CV joints			~
* = decals	sc 916			-Jul-	ELD SP*	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC * P * W S D						Performance	~		
		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	-	of tvre	es)
L/H tail light & reflector cracked . Detachable tow bar .									mm
						Right front			mm
						Left rear		3	mm
Condition	as During Pody Inc	oction	D.			Right rear			mm
Conditions During Body Inspection: Dry						Right rear 9 mm   Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy .	-	•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	h = l = = = = = du					Tail lights	~		
Carpets	hole on dr	ivers side .				Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Good 2WD d/cab ute .						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		I
Road Conditions During Test Drive: Drv						Central locking	~		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
L	-								_ <b>-</b>
Inspecte	Inspected by: Daryll Timms Date: 17 Aug 2018								

I have read and understood this condition guide.

Name: .....

Signature: .....