

Report ID: 18,330,522 Version: 2 Created: 05 Sep 2018

Make:	Opel	Model:	Astra	Body Style:	SUV		Pass	Fail	N/A
Year:	2,003	Registration:	FLI628	Reg Expiry:	25 Dec 2018	Engine			
WoF Expiry:	2,003 02 Oct 2018	Odometer:	126,967 Kms	Good No:	18330522	Oil level	~		
VIN:	W0L0TGF4835072433	Next Service:	126973	Service Histor		Smoke & fumes	~		
	W0E01014055072455		120975		. 110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends									
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
Key:			S			Performance	~		
S=scratch						Radiator / Hoses (visual)			
D = dent						Transmission			
R = rust	sc 96			$\langle \rangle \rangle$	SHUY	Operation	~		
PT = paint def	ect N					Noise	~		
C = crack	Ille]]]]]	Clutch			~
P = pin dent * = decals	sc dk			SI_	BHB	CV joints	~		
* = decals SW SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
					Left front 4.0			mm	
						Right front	4	.0	mm
						Left rear	5	5.0 mn	
Conditions During Body Inspection: Dry						Right rear	6.0 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation		~	
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Darkle	rd Good					Wipers (front & rear)	~		
Dashboa	iu					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking		~	
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 10	01,765	Reversing camera			~
Inspected by: Brian Hill Date: 17 Aug 2018									
I have read and understood this condition guide. Name:									