

Report ID: 18,330,987 Version: 2 Created: 20 Aug 2018

Make:	Ford	Model:	Mondeo	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,009	<b>Registration:</b>	FDY297	<b>Reg Expiry:</b>	06 Sep 2018	Engine	1		L
WoF Expiry:	09 Jun 2019	Odometer:	114,544 Kms	Good No:	18330987	Oil level	~		
VIN:	WF0DXXGBBD9R2240	Next Service:	122400	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
			S		S	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s sc			210	HIVS	Operation	~		
PT = paint def	ect NP				11111	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	s sc dl				24116	CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W – signinean			S			Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	3.0 mm		
						Right front	3.0 mm		mm
						Left rear	4	.0	mm
Conditions During Body Inspection: Wet						Right rear	4.0 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
Air Conc									
Operation							~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dastibua						Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet Central locking							~		
	ning Mashaulau	<u> </u>				Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									2
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			2
Inspected by: Xinghui Lin Date: 19 Aug 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....