

Report ID: 18,331,108 Version: 2 Created: 08 Sep 2018

Make:	Hyundai	Model:	130	Body Style:	Hatchback	1[Pass	Fail	N/A	
Year:	2,011	Registration:	GDZ320	Reg Expiry:	30 Nov 2018	lŀ	Engine			L	
WoF Expiry:	03 Feb 2019	Odometer:	82,519 Kms	Good No:	18331108	lŀ	Oil level	~			
VIN:	KMHDC51EMCU37464	Next Service:	85,000kms	Service Histor	y: Yes	lŀ	Smoke & fumes	~			
						ł	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						lŀ	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						lł	Cooling System	•			
						H	Coolant condition	~			
						ìŀ	Performance	~			
Key:		-0	P DSC			lŀ	Radiator / Hoses (visual)	~			
S = scratch						H	Transmission				
D = dent						lŀ					
						1	Operation	v			
PT = paint defect							Noise	~		<u> </u>	
C = crack P = pin dent						1	Clutch			~	
*= decals							CV joints	~			
SC = stone chips							Wheel bearings	~			
W = significant scuffs						╎╎	Brakes				
						╎╎	Performance	~		<u> </u>	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						╎╎	Hand Brake	~		Ļ	
Front left window fail from master switch						ļļ	Tyres (lowest observed tread depth of tyres)				
						ļļ	Left front		7	mm	
						ļļ	Right front		7	mm	
						1	Left rear	;	7	mm	
Conditions During Body Inspection: Wet						∐	Right rear		7	mm	
						il	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments							Suspension				
A/C belt cra	acks						Suspension performance	~			
							Steering performance	~			
							Shock absorbers	~			
							Air Conditioning / Heater				
							Operation	~			
Interior Comments							Electrical / Accessories		-		
Seats	Good						Head lights	~			
Carpote	Good						Tail lights	~			
Carpets						lſ	Indicators	~			
Panels	Good				[[Dashboard warning lights	~				
	, Good					ļĮ	Wipers (front & rear)	~			
Dashboa	ira					ļĮ	Window winder FL		~		
						¦	Window winder FR	~			
General Comments						ļţ	Window winder RL	~			
Head unit need codes Left front window not going up from master switch						ļţ	Window winder RR	~			
						ļļ	Rear view mirrors	~			
						ļļ	Radio (basic test only)		~		
						ļļ	CD (basic test only)		~	1	
						ļĮ	Number of keys	2		L	
Road Conditions During Test Drive: Wet						۱ţ	Central locking	~			
						ļ	Remote locking	~			
Engine Timing Mechanism: Cambelt						ļŀ	Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: No Kms:							Reversing camera			~	
								1	1		
Inspected by: Jason Law Date: 08 Sep 2018											
I have read	and understood th	is condition c	guide. Name: .				Signature:				