

Report ID: 18,331,196 Version: 1 Created: 20 Aug 2018

Make:	Volkswagen	Model:	Polo1.8T	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,008	Registration:		Reg Expiry:	nuceriouen	Engine			L
	2,008 14 Aug 2019	Odometer:	70,219 Kms	Good No:	18331196	Oil level	~		
VIN:	WVWZZZ9NZ8Y00328		80,213kms	Service Histor		Smoke & fumes	~		
	WWWZZZ9NZ810032c		80,21361115		y • NO	Performance	~		
Note: This report is not a warranty						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends									
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			1
						Coolant condition	~		
Key:						Performance	~		
S = scratch						Radiator / Hoses (visual)	~		
						Transmission			
R=rust						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch	~		
P = pin dent						CV joints	~		
* = decals SC = stone chips						Wheel bearings	<		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
						Tyres (lowest observed tread	d depth	of tyre	1 2S)
						Left front 6 m			mm
						Right front			mm
						Left rear	6		mm
Conditions During Pody Inspections						Right rear			mm
Conditions During Body Inspection: Wet						Spare	/		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Tidy.						· ·			1
nay.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		1
						Operation	~		
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	<		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			~
Nice little turbo hatch.						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		+
						Number of keys	1		1
Pond Conditions During Test Drives						Central locking	· ·		<u> </u>
Road Conditions During Test Drive: Wet						Remote locking	~		+
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:									-
			<u> </u>			Reversing camera			~
Inspected by: Daryll Timms Date: 20 Aug 2018									
I have read and understood this condition guide. Name:									